

Non-contact Photo Tachometer Adaptor

✓ **Measure from 100 to 19990rpm**
With 0.1mV/rpm output when plugged into a multimeter

Features:

- 1.2% basic accuracy
- Dims: 6.7x2.9x1.5" (170x74x38mm)
- Weight: 8oz (227g)
- Complete with 4.5ft (1.4m) cable and banana plugs, 23 (0.6m) reflective tape, and 4 AA batteries



Ordering Information:

461900Non-contact Photo Tachometer Adaptor
461900-NIST.....Non-contact Photo Tachometer Adaptor w/ NIST

